



## AEROGREEN AC-10

# AEROGREEN AC-10 RUST REMOVER AND METAL PREP

## READY WIPES

**AEROGREEN AC-10 Rust Remover and Metal Prep** Removes rust from metal surfaces and prepares the surfaces for new protective coatings. Ideal for all Industrial, Automotive, Agriculture, Transportation Industries and Marine Industries.



AEROGREEN AC-10 Rust Remover and Metal Prep is a phosphoric acid and detergent blend formulated to clean metal surfaces, remove rust, and profile steel, cast iron, galvanized metals, zinc, high polished aluminum prior to paint or to prepare a surface for a subsequent chemical coating, including liquid, and powder coating finishing systems.

For use in Wipe on Wipe off Preparation of Surface Prior to Painting

The rust must be removed to prepare the surfaces prior to painting or applying new protective coatings or the rust will continue to grow under the coating.

Underlying Rust



Rust under Paint



## AC-10 Rust Remover

For Cleaning All Types of Metal: Clean, prep and prepare metal surfaces for paint or powder coat and all types of finishes

On Steel: AC-10 Removes rust and flash rust from steel surfaces and leaves a corrosion inhibiting residue which prevents rusting aids in coating adhesion.

### Direction For Use:

1. Wipe surface using a AC10 Ready Wipes to remove all surface contaminates.
2. Turn the cloth constantly as you clean to prevent wiping surface with a contaminated side and to prevent cross contamination of soils from one area to the next
3. Use enough wipes to leave the surface visibly wet.
4. Wipe surface dry with clean cloth, No rinsing is necessary.
5. Once the surface is dry the metal is ready for the coating to be applied.

**AEROGREEN AC-10 AVAILABLE IN CONCENTRATE AND IN A VARIETY OF SIZES:** For use in steam cleaning/ pressure washing , cold or heated dip tanks or immersion tanks. Especially for heavy or sever rusted or areas where pitting has begun.

Using AEROGREEN with a nylon scrub pad dipped into the concentrated AEROGREEN AC-10 to remove the rust from the pitted area as you wet sand and smooth the surface with the nylon pad. Follow by using a clean dry cloth to to dry the surface and prevent rust from reoccurring

**SAFETY/CAUTION:** Rubber gloves are recommended to prevent drying of the skin. Goggles are recommended to protect eyes if splashing is expected. Harmful if swallowed. Avoid getting into eyes. If contact occurs, flush with running water. If irritation persists, get medical attention. May cause dryness of skin with prolonged use, wash hands with cold water and apply a hand lotion.

**FOR USE ON MILD STEEL, CAST IRON, ALUMINUM, GALVANIZED METAL, COPPER, NICKLE, BRASS, AND MAGNESIUM**

**Removing Welding Splatter:** To clean, prep and prepare freshly-welded metal for paint or powder coat finishes to promote excellent paint adhesion.

Wipe surface as soon as the surface is cool enough to touch with AEROGREEN AC-10 Ready Wipe. Follow by a dry clean cloth to wipe dry.

**Galvanized:** Improves the adhesion by removing the passivation film on the surface.

### Etching High Polished Aluminum:

1. Use a clean AEROGREEN AC-10 Ready Wipe to Wipe a small area at a time with the dampened cloth.
2. Wipe dry the same are with using a second clean, lint free cloth to insure the surface is dry and no residue is left on the surface



Aerogreen Solutions, LLC.  
1285 Brucetown Road P.O. Box 399, Clear Brook, VA 22624  
P. 540.450.8375 F. 540.450.8379 [www.aerogreen.us](http://www.aerogreen.us)